

Technical Specification		
Number of control axes	Milling system	Lathe System
Max. number of control axes (NC axes+Spindles+PLC axes)	6	
Max. number of NC axes	3	
Max. number of spindles	1	2
Max. number of PLC axes	2	
Number of simultaneous contour control axes	3	
Maximum PLC program capacity	8,000 steps	
Least command increment	0.1μm	
Least control increment	1nm	
Memory capacity	230kB [600m]	